


Received: 2/18/02 17:00;

-> PORTER INSTRUMENT CO.; Page 43

02-18-02 16:41 FROM-RATNER & PRESTIA

6104070701

T-246 P.043/056 F-983







FIG. 2

FIG. 3



02-18-02 16:41 FROM-RATNER &amp; PRESTIA

6104070701

T-246 P.046/056 F-883

FIG 4




FIG. 5






FIG. 6A

02-18-02 16:42 FROM-RATNER &amp; PRESTIA

6104070701

T-246 P-048/056 F-983





FIG. 7

FIG. 8




02-18-02 16:42

FROM-RATNER &amp; PRESTIA

6104070701

T-246 P.050/056 F-983







Fig. 10A



— 55





Fig. 10B




FIG 11.




Fig. 12




FIG 13

02-18-02 16:43 FROM-RATNER &amp; PRESTIA

6104070701

T-246 P.056/056 F-883


94F

Fig. 14